

# WEST Search History

[Hide Items](#) [Restore](#) [Clear](#) [Cancel](#)

DATE: Saturday, September 15, 2007

<u>Hide?</u>	<u>Set Name</u>	<u>Query</u>	<u>Hit Count</u>
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; THES=ASSIGNEE; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L47	L46 and (thick\$3 or flat\$3)	86
<input type="checkbox"/>	L46	thrust near2 (washer or bearing)with (hardness or hv or rockwell)	205
<input type="checkbox"/>	L45	L44 and hardness	22
<input type="checkbox"/>	L44	thrust near2 washer with thin	147
		<i>DB=USPT; THES=ASSIGNEE; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L43	5961218.bn.	1
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; THES=ASSIGNEE; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L42	L41 and (flat\$2 or thick\$3) and (hardness or hv)	42
<input type="checkbox"/>	L41	c75s	1376
<input type="checkbox"/>	L40	thin near10 washer with cold with (flat\$2 or thick\$3) and (hardness or hv)	0
<input type="checkbox"/>	L39	L34 and rockwell	11
<input type="checkbox"/>	L38	L34 and .001	0
<input type="checkbox"/>	L37	L34 and (flat\$2 or thick\$3) and (hardness or hv)	15
<input type="checkbox"/>	L36	thrust with washer and cold and (flat\$2 or thick\$3) and (hardness or hv)	57
<input type="checkbox"/>	L35	L34 and cold and (flat\$2 or thick\$3) and (hardness or hv)	8
<input type="checkbox"/>	L34	(sae or aisi)near5 1074	54
<input type="checkbox"/>	L33	L32 and thrust and (flat\$2 or thick\$3) and (hardness or hv)	34
<input type="checkbox"/>	L32	(384/121).ccls. or (384/107).ccls. or (384/112).ccls. or (384/123).ccls.	1201
		<i>DB=USPT; THES=ASSIGNEE; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L31	L30 and (flat\$2 or thick\$3) and (hardness or hv)	5
		(4806308   5912073   5996471   6231309   5891273   5363557   6296952	
<input type="checkbox"/>	L30	RE27081   4934442   3333579   5650025   5112416   5028393   5976711   5192136   5536587   5766778   5057274   5387461   6149310)![PN]	20
<input type="checkbox"/>	L29	("6511226")![PN]	1
<input type="checkbox"/>	L28	("6511226")![URPN]	2
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; THES=ASSIGNEE; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L27	6511226.bn.	2
<input type="checkbox"/>	L26	L25 and (lubricant or lubricat\$3)	82
<input type="checkbox"/>	L25	cold near2 roll\$3 and washer and (flat\$2 or thick\$3) and (hardness or hv)	241
<input type="checkbox"/>	L24	L22 and (lubricant or lubricat\$3)	28
<input type="checkbox"/>	L23	L22 and (planetary or epicycl\$3)	5

Γ	L22	thrust near2 washer and cold and (flat\$2 or thick\$3) and (hardness or hv)	46
Γ	L21	thrust near2 washer with cold and (flat\$2 or thick\$3) and (hardness or hv)	7
Γ	L20	thrust near2 washer with temper\$3 and cold and (flat\$2 or thick\$3) and (hardness or hv)	1
Γ	L19	washer with temper\$3 with cold with (flat\$2 or thick\$3) with (hardness or hv)	0
Γ	L18	thrust near2 washer and temper\$3 with cold with (flat\$2 or thick\$3) with (hardness or hv)	0
Γ	L17	thrust near2 washer with temper\$3 with cold with (flat\$2 or thick\$3) with (hardness or hv)	0
		<i>DB=USPT; THES=ASSIGNEE; PLUR=YES; OP=OR</i>	
Γ	L16	5489255.pn.	1
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; THES=ASSIGNEE; PLUR=YES; OP=OR</i>	
Γ	L15	L14 and washer	9
Γ	L14	volker near2 ploetz or wolfgang near2 fugel or alexander near2 reimchen or horst near2 engelhardt	76
Γ	L13	de-4029373-\$.did.	1
Γ	L12	de-4009968-\$.did. or de-4029373.pn. or de-3502076-\$.did. or de-19804734-\$.did. or de-19902565-\$.did.	5
Γ	L11	de-4029373-\$.did. or de-3502076-\$.did.	2
Γ	L10	5795258.pn. or 5302160.pn.	4
Γ	L9	L8 and cold near2 roll\$3	3
Γ	L8	thrust near2 washer with grind\$3	40
Γ	L7	l4 and thrust near2 bearing	0
Γ	L6	l4 and thrust near2 washer	0
Γ	L5	cold near2 roll\$2 with vibrat\$5 near5 grind\$2	0
Γ	L4	cold near2 roll\$2 with grind\$2	163
Γ	L3	l2 and (thick\$3 or flat\$3)	3
Γ	L2	c75s with steel	13
Γ	L1	c75s with (thick\$3 or flat\$3)	2

END OF SEARCH HISTORY